

SQUEAK AND RATTLE SERVICE TIPS

BULLETIN:

NV005-00

GROUP:

NVH

DATE:

March 10, 2000

TITLE:

SQUEAK & RATTLE SERVICE TIPS

MODELS:

'00 Celica

Introduction To reduce interior squeaks and rattles on the 2000 model year Celica, noise-absorbing materials have been added between parts at several locations. The following repair procedures have been adopted.

Applicable Vehicles

2000 model year Celica.

CONCERN	STARTING VIN (GT)	STARTING VIN (GTS)
Front Roof Headlining Rattle Noise	JTDDR32T0Y0011172	JTDDY32T6Y0006450
Sliding Roof Rattle Noise	JTDDR32T0Y0011172	JTDDY32T6Y0006450
Back Door Front Left Area Rattle Noise	Field Fix Only	Field Fix Only
Back Door Trim Rattle Noise	Field Fix Only	Field Fix Only
Package Tray Trim Rattle Noise	JTDDR32T8Y0015891	JTDDY32T2Y0009541
Luggage Compartment Rattle Noise around Tie-down Hook	JTDDR32T0Y0016520	JTDDY32T8Y0009995
Buzz Noise from Instrument Panel	Field Fix Only	Field Fix Only

ZOOM

SIZED FOR PRINT

Production Change Information

Parts Information

PART NUMBER

08231-00801

90467-07152-CO

PART NAME

Interior Noise Kit

Clip



OPCODE	DESCRIPTION	TIME	OPN	T1	T2
BD9019	Lower Front of Headliner To Add Urethane Sponge to Electrical Connector	0.5	82171-2B170	91	44
BD9020	R & R Moonroof To Add Felt To Clip	0.2	90467-07152-C0		
BD9021	Add Felt To Electrical Connector	0.1	82184-202X0		
BD9022	R & R Back Door Trim To Add Felt	0.2	67751-20010-B0		
BD9023	Add Felt To Package Tray Trim	0.1	64330-2D430-B1		
BD9024	Tap Tie-Down Hook Bolts To Reduce Rattle	0.1	90105-06130		
BD9025	Add Tape To Hood Lock Control Cable	0.1	53630-20610		

ZOOM

SIZED FOR PRINT

Warranty Information

Applicable Warranty*:

This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint